

South Terminal Apron Rehab – 2024

Key Aspects

- ~3' of undercut replaced with new sand, stone, asphalt.
- 75,000lb load bearing capacity
- Services transient jet parking ramp
- Services taxiway access to new main entrance hangar site (hangars 38-40)

